

HM 1000 1250 1250W

Date		Corrections			
	Page	Contents	AS-IS	TO-BE	Reason
2015-10-14		Version	150923SU	151013SU	
	6р	Machining Performance >	Cutting Depth 1.7(0.1) Chip removal rate 1176	Cutting Depth 1.7 (0.067) Chip removal rate 40.8 (2.5)	Error change